


05830744.00160
T02T004T/03850






Figure 2

Trunk Receiver




FIG. 3

Multi-rate Clock / Data Recovery Circuit with 2R Bypass Mode




FIG. 4




Figure 5